SSA3000X Firmware Revision History

Version	Revision
V2.1.1.4 2023/7/10	Notice: This firmware must be upgraded from v2.1.1.1 or later. If your analyzer has an earlier version, don't use this FW to update. Solved Issues: • Fix the problem that the bandwidth of the emi filter in SA mode • Fix the problem that setting the TG Level in SA mode may cause TG to have no output • Fix the problem that the n dB Marker measurement results in SA mode are inconsistent with the OBW measurement results • Fix the problem that there is an invalid frequency menu in Harmonic in SA mode • Fix an issue where 'micro' relative units represented by 'u' were not recognized when reading files
V2.1.1.3R1 2022/6/10	Notice: This firmware must be upgraded from v2.1.1.1 or later. If your analyzer has an earlier version, don't use this FW to update. Improvements: • Optimize the Ref level and Att couple Solved Issues: • Fix the zero sweep type when fft in SA mode • Fix the OPC response in EMI mode
V2.1.1.1 2022/4/7	The v2 version is the first time introduced. It was not able to update from any earlier version. It was aligned with v3.2.2.5.1R1.r1 of SSA3000X Plus.